

The main condenser tubes were cracked and wasted  
in way of packing. The section of tubes between the tube plates

was found reasonably good.

WOKINGHAM COPY.

21st October, 1941.

Dear Sir,

I duly received your letter of the 16th instant  
respecting the steamer "EMPIRE TARPON" and as the Machinery  
Survey for reclassification was held only a few months before  
the Glasgow survey was commenced, some explanation of the  
rapid deterioration indicated is desired and the Surveyors  
should furnish this if possible.

I am, Dear Sir,  
Yours faithfully,

Clerk to the  
Classification Committee.

The Secretary,  
GLASGOW.



© 2020

Lloyd's Register  
Foundation

W34-0092

as far as now seen is in  
opinion to remain as classed and to have the notation