

S.S. "LAVEROCK"

Submitted a copy of the letter from the Owners Superintendent be sent to the Glasgow Surveyors for their remarks. They should be informed that the tank side and lugs are thickly cemented, which it is stated was done when the vessel was built. They should be asked to ascertain if this was an Owners requirement or under what circumstances it was done.

E. L. L.
4. 8. 14



© 2020

Lloyd's Register
Foundation

W340-0010