

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME STEEL S.S. "BEECHPARK"  
(Ex "WAR CEDAR")

Report Grk.

No. 17503

**For the CHIEF SHIP SURVEYOR**

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/12.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

The Downcom Pump has been dispensed with for the present.

\* 100 A.1. (steel)

1 DK (steel) and Platform DK (steel) in Nos 1, 2, 4 & 5 Holds.

Longitudinal framing in Double bottom & at Decks.

Cell DB 347' 1296t. FPT 125t. APT 200t.

FK. 7BH. pl.com. Lloyds A&CP. P 51', B 114', F 39'

The Certificate of Classification, to be endorsed  
"Cargo battens not fitted," and the same  
notation to be printed in the Register Book.

CVS.

8-8-19



© 2020

Lloyd's Register

W347 0623