

Received from Chief Surveyors

Steel & S. "OLYMPIER"

Report Als.

No. 40166.

For the CHIEF SHIP SURVEYOR

I have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case which the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.02.)

When due

DO A.1. (steel).

Dks (steel)

DB 342' 920t. DTa 30' 850t. FPT 122t. APT 104t.

"Intermediate Tween deck BH in after hold disposed with"—
"1 BH to 2nd Dr only" Cern. Lloyd's ATCP. P37, B120, F45'

It is required to state length of dry tanks under Boilers. They
are to forward letter from owners concerning omission of tween deck bulkhead in after hold.

Als
15-7-20

300105333