

If so, in

1m,4,34.

4 E

Received from Chief Engineer Surveyor

Received by Chief Engineer Surveyor

VESSEL'S NAME

"OTTERPOOL"

Rpt.

Off.

No. 53433

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

REPAIRS TO ENGINES ~~AND BOILERS~~ DUE TO DAMAGE THROUGH ENEMY ACTION.

Screw shaft and sea connection examined and a new propeller key fitted.


A second hand dynamo set now fitted.

It is submitted the vessel is eligible to remain as classed, with notation S 5.40.

The Surveyor should be requested to stated if the new dynamo set is additional to the existing one or whether it replaced it.

Replace

W 29/5/40



© 2020

Lloyd's Register

Foundation 23.5.40

W350-0058