

Surveyors

Received from Chief Surveyors

NAME *Stl S* "PLANTER"

Report *Stl*

No. 47211

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.6.02.)

1st Entry

When due *old* Rules

✱ 100 A.I. (Steel).


2 D^{rs} (Stl).

Cell D.B. 361' 1170 t, D.T.a 32' 911 t, F.P.T. 635, A.P.T. 265.

F.K, 8 B.H. (1 B.H to 2nd D^{rs}), pt Cen, Lloyds A.C.P.

P 37', B 139', F 44'.

Concluded that ceiling is fitted ~~under~~ ^{above} the hatches and as the H. 11.21.
as shown on the approved plan but the surveyors should be
led to state if this is so.



© 2020

Lloyd's Register
Foundation

W350-0082