

S.S. Ciudad de Reus

It is submitted The Daring Surveyor should be informed that the whole of the Engines require to be examined except the screw shaft which was examined August 1910, The bedplate of the main engines requires to be renewed, & the Monkey Boiler Survey held on its integrity. It is also considered that it would be advisable for the main ^{which were damaged in March last} rollers to be again examined so that a fresh record of survey can be assigned.

It should be pointed out to the Daring Surveyor that the forward end of the A.P. Crankshaft was cracked at Barcelona on March last ~~the~~ on consequence of the crank pin being burned down to $9\frac{1}{4}$ " The main rollers pressure was reduced to 50 lbs.

ARR

30.9.11



© 2021

Lloyd's Register
Foundation

W362 B15-0011