

S.S. "ARMONIA".*Orig. in M. Rep.*

The plan of the pumping arrangements has been examined and found to comply with the Rules, except that a sluice valve is fitted to the collision bulkhead and no bilge injection is shewn.

It is submitted that provided the sluice valve on the collision bulkhead be dispensed with and a hand pump suction be fitted to the fore peak, and a bilge injection, if not already in the ship, be fitted, this pumping arrangement would merit approval.

Particulars of the engines and boilers should be furnished and if they are found to comply with the Society's Rules and on examination by the Society's Surveyors they be found to be in good and safe working condition, it is submitted they should be approved.

31.12.14.



© 2021

Lloyd's Register
Foundation

ARMONIA

Gen 6319

Guard Book Book 9



© 2021

Lloyd's Register
Foundation