

2m, 3, 10.

Florence Luckenbach

1

Sent to Chief Surveyors

8/6/10

Received from Chief Surveyors

VESSEL'S NAME

St Ad Damara

Report

Gls

No.

28948

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

When due

+ 100A-1. (Plat)

2 Dns (ott)

WB. Bull DBA 13' n 60B42 f181 9946 F.P.T.1416 A.P.T.2656
 FK. 6BH. Cum. Lloyd's at 60 PHO B 125 F38

M

RBA

8/6/10

It is concluded that the tank top plating is ^{thick} 140 for
 2 lengths ~~as~~ as far as on the approx midship section 124.36
 as stated on the report, but the surveyors should state
 if this is so.



© 2019

Lloyd's Register
Foundation

W37-0160

Spacing
 PILLARS, In 'tween Deck, size and spacing

50 50 50 50 50 50

Deck. Material and thickness
 Forecastle Deck Stringer Plate, b'dth & th'kns