

Chief Ship Surveyor _____

Received from Chief Ship Surveyor 3 APR 1941

NAME CLAN MACNAB. Rpt. Bom. No. 6402

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey _____

RETAIN

The Bombay Surveyors report this vessel placed in dry dock, bottom cleaned and coated, repairs to some pitted shell plates and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 1.41 as recommended.

100 A 1
Awng. deck with fld.
Fitted for oil fuel etc
1.41 Bom.



© 20
Lloyd's Register
Foundation

The vessel appears to have been torpedoed as noted in pencil on report