

State latest date of inspection  
Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

W383-0043

1914.34.

4 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "DUNGENESS".

Rpt. Hul. No. 50656.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

RETAIN

A new dynamo set fitted.

It is submitted the vessel is eligible to remain as classed with record LMC 11,39, subject to the electric installation being tested.

It is submitted the Surveyor be requested to state what arrangements are proposed for the electric installation being megger tested.

on Admiralty Service  
See LK 5/6/40

Lloyds Register Foundation  
24.5.40.