

Surveyed Afloat or in Dry Dock? *none* Name of Dock *none* Particulars of Classification (which must be precisely as in Register Book & Supplement)
Cell D/Bor D/Ba feet; uE&B feet }
total capacity tons. FPT tons; APT tons; MT feet tons }
CHARACTER. for Special Survey.

3m, 11, 30.

2 - APR 1940

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "EMPIRE CONVEYOR" Rpt. NWC No. 98346

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Newcastle Surveyors report the vessel placed in dry dock, the bottom coated, a chain cable joining shackle renewed, some steering chains hatch covers, ventilator coamings renewed and minor repairs carried out.

The auxilliary steering gear, consisting of tackles, etc. have been renewed.

Shell plates F.5, G.4 & 5, H.6 and framing in way P.S., F.4, G.5, H.4 & 5, J.4, framing in way, Starboard side, were found to be slightly indented.

The Surveyors recommend the indented side plating etc. in way of No. 1 hold P. & S. be dealt with at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed with Record of Survey 3.40, subject as recommended.

100A1)
Shelter deck with Freeboard.) Subject, etc.
3.40 SHL)

[Signature]
29.3.40



© 2019

Lloyd's Register
W387-0159
Foundation