

Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "EMPIRE MINIVER" Rpt. Mch. No. 10182

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/1924)

Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~


Survey for reclassification partly held.

Minor repairs for wear and tear.

It is submitted the vessel ~~will be eligible for the record~~  
 WILL BE eligible for the record ~~ELMC~~ 8.40 on completion.

To complete the survey:- See report.

For S.R.L:- Bs 8.40, S 5.40.

Fees.

W 388-0230

Lloyd's Register  
Foundation

13.9.40.

(situated in 'Deep Tank'). Windlass. Steering gear.  
 General Observations, Opinion, and Recommendation:— The machinery of this