

veyors  
Received from Chief Surveyors

ME Steel S.S. "WEST COBALT". Report Pld. No545

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

ases which have to be submitted to the Classing Committee" the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 245192.)

When due

The anchors have been tested by Surveyors to the American Bureau and the chains at Tipton, Sunderland, and Low Walker.

The kedge anchor has been dispensed with as a War Emergency Measure.

It is not stated whether a stream chain or wire has been supplied.

100 A.1. (Steel).

2 Dks. (Steel).

Cell DB 356' 1139t. MT 29' 745t. FPT 132t. APT 143t.

FK. 7 BH. pt.Cem. Lloyd's C.P. P44', B115', F47'.

M

25. 3. 19.

It is concluded a stream chain or wire has been supplied as required, but the Surveyors should state if this is so.

S.O. 11/5/19

All better  
27. 6. 19

M



© 2020

Lloyd's Register Foundation

Spacing	7	3.438	18.6	7	3.438	18.6	Deck. Material and thickness	35 x
BEAMS, Bridge Deck, Angle, Ball, Angle, Plates	✓			✓			Forecastle Deck Stringer Plate, b'dth & th'kns	3 1/2 x 3 1/2
Tea Ball, or Channel								
Angles on upper edge								