

4 E

Engineer Surveyor

Received from Chief Engineer Surveyor

"EMPIRE VOLUNTEER".

Gff.

No. 53560.

Rpt.

The Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points stated in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

SURVEY FOR RECLASSIFICATION PARTLY HELD.

Wear and tear repairs:- Some boiler stays and tubes

renewed; a furnace repaired.

To complete the survey:-

Engines: All requirements to be carried out except examination of sea connections and the H.P. and M.P. slide valves.

Boilers: Drain plug of the centre boiler to be examined and dealt with as necessary.

It is submitted the vessel is eligible for the record

examined 8,40.

For S.R.L.:- S 7,40.


9.8.40.



© 2020

Lloyd's Register
Foundation

W 389 - 0129

The machinery of this vessel, so far as ...
to have attention + L.M.C (class contemplated), and record