

Subject to indented bottom plating forward and N° 5 plate from aft in 1<sup>st</sup> stake  
below sheer (P.S.) and rudder plate, set over, being dealt with at the first convenient  
opportunity. Bower anchor + 2 lengths of cable to supply.

11

W 394-000 4  
SPT 727-339

of Ship Surveyor

Received from Chief Ship Surveyor

NAME **FIRCREST**

Rpt. **Nwc.**

No. **98463**

ks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also  
to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points  
presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

rey **DOCKING AND ALTERATIONS**

The **Newcastle** Surveyors report this vessel placed in  
dock, bottom cleaned and coated, ~~repairs or renewals to~~  
~~minor repairs effected.~~ *a bower anchor supplied.*  
*new accommodation now transferred from f'cle to poop with structural additions.*

It is submitted the vessel appears worthy to remain as  
assessed with record of survey **4-40** as recommended *subject as above,*  
*except as regards*  
*bower anchor*

100 A.I.  
4-40 Nwc. } *Subject, etc*


*was*

*2-5-40*

© 2020

*Delete from S.R.L. bower anchor*  
*Insert cables in stables*

*notes in italics*  
*just*



Lloyd's Register  
Foundation

W 394-000 4

Bottom Plating

and found efficient?

Stringers, Clamps & Shelves

Hawser

Standing