


shaft now been changed? If so, state reasons

s/s "Preradovic"

Port. 16722.

It is concluded that spare top & bottom
 end connecting rod bolts & feed & bilge
 pump valves are on board but the Surveyors
 should be requested to state if this is so.

Ln 201917



© 2020

8/9/27

Lloyd's Register
 Foundation

W 394 - 00 83