

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

30 OCT 1950

SHIP'S NAME "FLASHLIGHT" Rpt. Sld No. 32964

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The SUNDERLAND Surveyors report this vessel afloat and on account of collision 2 shell plates repaired and the port hawse pipe renewed.

It is submitted the vessel is worthy to remain as classed without record of survey.

W.S.
.....
27.9.40

The Certificate of Classification to be endorsed "Cargo Bullets not fitted" and the same notation to be printed in the Register Book.



© 2019

Lloyd's Register
Foundation

W395-0155