

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ☒ and of the Donkey Boilers? ☐
Surveyor examine the drain plugs of the Main Boilers? ☒

2 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Gracia

Rpt.

Recd

No.

10415

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/92.)

of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 2

^{boiler}
This Survey, due 1/4/11 now held ^{now}
_~ partly

completed, and the following repairs carried out (due to ^{by enemy action} damage caused):-
engines, auxiliaries, pumps, boiler opened up throughout. Shafting checked. All pumps placed in
Boiler mountings thoroughly overhauled & placed in order. Pumping arrangements
Steam piping tested & electrical installation placed in order. Fuel tank casing? removed as
machinery tried under working conditions & found satisfactory. Holding necessary.

It is submitted the vessel is eligible to remain as classed, with
notation of + Line 2.41. S. 9.40 as recommended.

W 398-0012

LMC 140 lb., F.D., &c.)
CS 3,34,

and condition & eligible, in our opinion, to remain as classed & to have
to be + LMC 2-41 & CL 9/40.

© 2020

Lloyd's Register
Foundation