

Repairs:- Both rudders and upper stocks removed, upper stocks built up

1m.3.42

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME ARRIAGA

REPORT Bal. No. 7688

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.) (Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DOCKING & ALTERATIONS ~~When due~~


Noted.

31.7.42

Wab

(No plans of alterations attached, consequently this part of report not dealt with.)

VESSEL SUNK, WAR LOSS.



© 2021

Lloyd's Register
Foundation

W4-0157

Inner Bottom Plating.....

and found efficient?

Air and Sounding Pipes

Good

Stringers, Clamps & Shelves

Salting

(State if examined.)

Standing and Running

Sails