

REPAIRS, OR EXAMINATION AS PER RULE, FOR DOCKING

5m.10.38.

23 OCT 1941

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME ARUBA

Rpt. Hul

No. 51351

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 2nd S.S. No. 3 became due 4.41.

For conditions of class and outstanding repairs see Endorsement 4.6.41.

The HULL Surveyors report the vessel placed in dry dock, bottom coated, and minor repairs effected.

It is submitted action be deferred.

(DOCKING DATE 10.41).

[Signature]
21.10.41

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register
Foundation

W4-0186

this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."