

S.S. Hurunui

It is concluded that a Spare <sup>Lubrication</sup> Oil Circulating pump is fitted as no mention of spare parts for these pumps is made on the report.

The Mdb. Surveyors should state whether this is so & whether the screw shaft is fitted with a continuous liner

W402-0086

R. M.  
31/1/21