

3m,11,39.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME \_\_\_\_\_ "HUMBER ARM" \_\_\_\_\_ Rpt. \_\_\_\_\_ Hfx \_\_\_\_\_ No. 3080

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs to after peak tank top and wash plate at the first convenient opportunity.

The Halifax N.S. Surveyor now reports the vessel afloat and on account of damage during heavy weather 2 lifeboats and missing equipment replaced and davits repaired.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as above.

As Now, Subject, etc.

*Sgt.*  
18. 6. 40



© 2020

Lloyd's Register  
Foundation

W 404 0104