

Chief Surveyors _____

Received from Chief Surveyors _____

SHIP NAME Steel S.S. "HARMODIUS". Report Cls. No.39259

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—Extract from Sub-Committee's Report, 24/5/92.)

of Survey _____

When due _____


The downton pump has been dispensed with for the present, and *it is* the Owners are agreeable to fit same if requested to do so.

✱ 100 A.L. (Steel).

2 Dks. (Steel).

Cell DB 340' 1142t. FPT 121t. APT 177t.

EK. 7 BH. pt.Cem. Lloyd's A.& C.P. P49', B127', F39'.



6. 11. 19.

It is concluded that the butts of D strake are quadruple riveted and the thickness of the stiffeners to the midship bulkheads as required, and the length of the bridge 126.6 ft. and not 12.66 as stated, but the Surveyors should state if this is so.

L. Sls. 14/11/19



© 2019

Lloyd's Register
Whob-0131
Foundation