

Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME s.s. 'ROJO' REPORT Cpn. No. 12527

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Survey..... When due.....

The class is subject to repairs to keel plate No. 2 and shell plate A.2 (s.s.), also to hatchway coamings, at the first opportunity, and to (a bower anchor being supplied).

A letter dated 13.11.48. has been received from Mr. Lydersen in which he advises a clerical error with regard to dates on the above report.

IT IS ACCORDINGLY SUBMITTED this ship is worthy to remain as classed, with record of docking 10.48, subject as above.

10.48 Cpn. Subject.

IN S.R.L.:

(Bottom is set up).

CARGO BATTENS NOT FITTED.

Ly.  
19  
11  
48.



© 2019

Lloyd's Register  
Foundation

W 412 100 55

I am, With kindest regards,

M.  
F on Felt.)