

Vessel placed on drydock. Bottom and Rudder cleaned, examined and coated.

Cables ranged 240 Fath 1-11/16" to 1-13/16" dia 5 anchors

3500,9,35.

2

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

St. Twin Is BEULAH

Report

S. To

No.

7706

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

2nd

No.

1

SURVEY PARTLY HELD.

4 Deep tanks tested

When due

10-37

When proposed to be completed

at next dry docking.

Portion of Survey held, &c.

To complete the Survey:- See Report.

REMAIN

WAB JLD

737 S. To



© 12937

Lloyd's Register
Foundation

W425-0083

This vessel is eligible in my opinion to remain as classed with fresh record

to be assigned in completed