

Did the Surveyor examine the Safety Valves of Donkey Boiler? **Yes**

To what pressure were they afterwards adjusted under steam?

2m. 5.31.

at to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Breiah

Report

540

No. *7706*

For the ~~CHIEF SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

C.S.

No.

1

SURVEY PARTLY HELD.

When due

10 37

When proposed to be completed

Next dry docking

portion of Survey held, &c.

See report.

Woud

Run

9.9.37



Lloyd's Register
Foundation

W425-0087

Records of the U. S. (NEW) 1-37, D. B. S. 6-37 and notation of L.M.C. and date when the

has been completed

RETAIN



© 2020

Lloyd's Register
Foundation