

No.

No. of Donkey Boilers  
Steam Pressure—  
in Main Boilers

Managers *of Good Hope*

If Surveyed Afloat or in Dry Dock Afloat

Port PANAMA

Voyage

Particulars of Classification (which must be  
precisely as in Register Book & Supplement)

Machinery  
including

L.M.

9.3

BS 9

S OG

L E

5a  
B.NOV

Steel Tw. Sc. M.S. "BEULAH"

S. Fo. No. 6845

The San Francisco Surveyors report that on account of damage caused by over salting, combustion chamber plates and <sup>of Donkey boiler</sup> furnaces were found buckled and tubes leaking.

Owing to the extensive repairs which would be necessary to repair this boiler, another boiler has been fitted in the vessel. This boiler, not built to class, has been examined throughout and tested hydraulically, and found or placed in good condition.

IT IS SUBMITTED that this vessel is eligible for the record D.B.S. 12,32 subject to two 2½" safety valves being fitted and adjusted under steam on vessel's return in about 3 months.

*Kru*

4.2.33

NOTE: - D.B. '14 fitted 12,32 W.P. 150 lb.

*D.B. 14 fitted 32*

and date, subject to two 2½" safety valves being installed and adjusted under steam on vessel's return to this Port in about three months.



© 2020

Lloyd's Register  
Classification

W425-0113



