

Engines made at \_\_\_\_\_ By whom \_\_\_\_\_  
 Boilers, when made (Main) ✓ \_\_\_\_\_ (Donkey) \_\_\_\_\_  
 \_\_\_\_\_ address \_\_\_\_\_

*n 24752*

# Lloyd's Register of Shipping.



Port of Rotterdam.  
Bucket Dredger  
 8th August, 1936. Rotterdam  
 No. 18731  
 No. 57064

Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.  
 The undersigned to maintain a succinct summary of any repairs that have been required and to forward the copies of such reports, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the abovementioned. - Extract from Sub-Committee's Report, 24/5/35.

Type of Engine Non Propelled

**This is to Certify** that  
Jan van Halbeek,

the undersigned Surveyor to this Society did at the request of the Builders survey the Steel Non-Propelling Bucket Dredger, Yard No. 520, during construction at the N.V. Scheepsbouwwerf & Machinefabriek "De Klop" at Gliedrecht.  
 If Boilers fitted with forced draught  
 If fitted with a continuous liner  
 If fitted with an outside glass  
 The Dredger will be recommended to be classed in the Society's Register Book as LOCAL "Dredger", subject to the following items being completed in the United Kingdom to which the vessel will proceed:-  
 Equipment to be approved and to be applied and verified.  
 Skylight and top plating of casing top above engine and boiler space to be riveted, and the approved plans, and it is submitted she is all pumping arrangements to be completed. 10.36

*Letter for 10.36*  
*W. H. van Halbeek*  
*J. van Halbeek*  
*25.8.36*

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Survey Fee <sup>10</sup> 5.35.  
 Special Damage or Repair Fee (if any) £ \_\_\_\_\_  
 Travelling expenses (if chargeable) £ 5.00

Received by me,  
 7.9.1936

Lloyd's Register Foundation  
 W 425 0213

Engineer Surveyor