

2m.4.31.

5E

9 NOV 1932

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Ambassador.

Rpt.

hwc

No. *89348*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02).

~~DAMAGE & WEAR AND TEAR.~~

Signature of Surveyor

*Superheaters fitted to all main boilers.
Port engines examined, & necessary alterations
made
Minor wear and tear repairs effected*

It is submitted the vessel is eligible to remain as classed with out
record of Survey as recommended.

*Y. R. M.
8.11.32*




© 2019

Lloyd's Register
Foundation

W426-0214

RETAIN

RETAIN



© 2019

Lloyd's Register
Foundation

When

A
1st
2nd
3rd
Collec
Stre
Ked

er of
ate.

m Chain
Wire...

Donkey B
Pressure
Main Boile

Donkey B

t Rep
rticul

dical Sur
e of Repa
nt of Da
es being
and init

mage cas
fered his

a damage

e Surveyor

was not d

hat parts

hat specia
eyor to as

e Surveyor

e Surveyor

Surveyor

Surveyor

Surveyor

Surveyor

rew shaft

shaft now

e shaft n

he distanc

Survey is

w a

tsi
sp
to ll
to ll
valu
ved
val
a. (a
eral
ate clear
any
140 W
ow
esh