

10.38.

23 OCT 1939

ived by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SSEL'S NAME "TORCHBEARER". Rpt. Sld. No. 32722.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Sunderland Surveyors report that while heaving anchor the 1st length of port chain cable broke and the anchor was lost.

A new bower anchor and length of chain cable have been supplied.

It is submitted the vessel appears worthy to remain as classed without record of survey.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

23.10.39



© 2019

Lloyd's Register
Foundation

W433-0121

Transverses.....
Floors.....

cient ?
Have Watertight Doors been examined and found

Breasthooks & Stemson

length.....
(on d