

5, Hamilton Terrace,

11 DEC 1939

4 E

by Chief Engineer Surveyor \_\_\_\_\_

Received from Chief Engineer Surveyor \_\_\_\_\_

'S NAME "TOGIMO".

Rpt. Mil. No. 5531.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey ~~REPAIRS TO ENGINES AND~~ BOILERS DUE TO DAMAGE THROUGH THE BREAKING OF  
A SCREW STAY.

Defective screw stay renewed and other minor repairs, effected.

It is submitted the vessel is eligible to remain as classed without fresh record.

W433-0176



Lloyd's Register  
Foundation

9.12.39.

*DOCK*

*in Store*