

ER. Dunder Grem Line Office

Surveyors 4/6/92

Received from Chief Surveyors

NAME Hungarain

Report Jun No. 5750

100A  
SS 46

the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR are desired on this Case for the consideration of the Classing Committee.

The requirements of the Rules for SS No 3 have been complied with.

30 fms of chain cable require to be renewed and this is proposed to be placed on board on the vessel, return to under in about a months time, when a new  $3\frac{1}{2}$  steel wire hawser stated to have been put on board require to be seen.

The partition bulkhead in fore hold is found to have been removed at some previous time and the record of bulkhead shored therefore be amended to 4 B.H.

The double bottom under machinery space has been repaired and the particulars of same shored up re-entered in the Register Book

It is submitted the vessel appears worthy to remain classed 100A.I. as recommended and when the 30 fms chain cable has been supplied & the  $3\frac{1}{2}$  wire hawser seen as required to have record of survey 5.92 & S.S. Den No 3 - 5.92

B.H

n 84B46



© 2019

Lloyd's Register  
Foundation

w437-0291

Observations, Sponso

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "9.91," or "to remain as classed and to have record of survey, 9.91, and the notations of No. 1-91 and ptND91, &c."