

No. of Main Boilers
o. of Donkey Boilers
Steam Pressure—
in Main Boilers

180

Owners

Managers

W. P. Ryan & Co. Ltd.
W. P. Ryan & Co. Ltd.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port London

Voyage

1m.2.32

27 OCT 1932

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

ESSEL'S NAME

Castle moon

Rpt.

hwc

No. 89297

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Signature of Surveyor

COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS~~ FOR S.S. No.

This Survey, due 12.32 ~~partly held at~~

now

completed, and the following repairs carried out (due to ~~grounding damage~~)

Screw shaft examined Port engine examined and repairs effected to crank shaft bearings

Superheaters now fitted to port & starboard boilers

It is submitted the vessel is eligible to remain as classed, with

notation of

B. 10.32

as recommended.

S. 10.32

YRM

27.10.32



© 2020

Lloyd's Register
Foundation

W439-0119

Ports B.S. 10-32 and Tail shaft seen 10-32.