

examined and tested. All summer tanks cleaned, examined and tested. Cofferdams cleaned and tested. Deep tank aft cleaned, examined and tested. Engine room double bottom tanks,

1935.

Chief Surveyors 9. 6. 36

Received from Chief Surveyors

SEL'S NAME M. T. SVEABORG Report L. F. No. 7520

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ure of Survey Damage + 1<sup>st</sup> S.S. No 1 When due 6.35 Lot 9928

*Subject to the indented bottom plating being jaired at the Owner's convenience.*

*Special Survey to date from 6.34.*



© 2023 10.6.36

Lloyd's Register Foundation

W439-0216

Survey Fee (per Section 29) \$325.00

Fees applied for,