

Apt. 8.

REC'D NEW YORK

MAR 11 1942

(Received at London Office)

- 9 MAY 1942

No. 7644

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 6th March, 1942 When handed in at Local Office 10th March, 1942 Port of Baltimore, Maryland

No. in Reg. Book. Survey held at Baltimore, Maryland Date, First Survey and Last Survey 14th Feb. 1942

on the Wood Iron or Steel T.S.M.V. "HEINRICH V. RIEDEMANN" (No. of Visits 1)

TONNAGE:—

GROSS 11020

UNDER DK. —

NET 6749

Built at Vegesack

By whom Bremer Vulkan

When 1930

MONTH. 11

Owners Panama Transport Co.

Owners' Address —

(if not already recorded in Appendix to Register Book).

Port belonging to Panama

Managers —

Surveyed Afloat or in Dry Dock? Afloat Name of Dock General Ship Repair Destined Voyage —

Cell DBor DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 3456 Port Rio

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified

Oil Engines
Continuous Survey
5 1/2 ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Equipment

One bower anchor placed on board to replace same stated to have been lost (for particulars please see table on back of report.)

34 fathoms chain cable stated to have been lost at same time not now obtainable, but it is stated will be supplied first opportunity.

Spare bower anchor
to be tested and so
fine chn. cable to
supply first opp.
Repair steam-driven
dynamometer first
opp.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Blanking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawser & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

The equipment of this vessel being now so far as seen in good condition, the vessel

appears worthy to remain as classed without fresh record of survey subject to 34 fathoms of chain cable being supplied at first convenient opportunity.

Survey Fee (per Section 29)	£	—	Fees applied for, Mar. 6, 1942
Special Damage Repair Fee (if any) (per Sec. 29)	£	30.00	Received by me, 19
Travelling Expenses (if chargeable)	£	1.50	
Second Surveyor's Fee (if any)	£		

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned As un

NEW YORK MAR 18 1942

Without burden.
ANCHOR

Subject Equip.

Lloyd's Register
Foundation

W44-0005

A 304

Lloyd's Register
Foundation