

If the tanks examined. Also state the amount of deterioration (if any) found in the girders, and of the inner bottom plating, especially in the boiler space.

Last Report No. 11235 Port Liu

100
5.38
No. 3
No. 1

COPY.

Lloyd's Register of Shipping,

High Close, Wiltshire Road,
Wokingham, Berks.

29th January, 1940.

R. Dear Sirs,
With reference to the classification in this Society's Register Book of the steamer "CEDRINGTON COURT", which, it is noted with much regret, is reported to have sunk following an explosion off the southeast coast on the 7th instant, I have to acquaint you that it is proposed to make a record of "Sunk - War Loss 1,40" against the vessel's name in the Register Book, but before taking any action, I shall be glad to learn whether you have any objection to this course being adopted in this instance.


An early reply on this point will be appreciated.

I am, Dear Sirs,

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. Haldon & Philipps, Ltd.,
1, LEADENHALL STREET,
E.C. 3.



© 2021
Lloyd's Register
Foundation
W440-0045

Sunderland