

SUNDERLAND, N^o 32624

Rpt. 14.

Port of Sunderland
January 11 1939

REPORT ON MASTS, SPARS, AND RIGGING.



Dear Sirs

Having, in accordance with your instructions,

examined the Masts, Spars, Iron Work of same, and Rigging, of the

(Name of Vessel) S/S Bedrington Court Lyng in the South Dock
on the (Date of examination) January 11 1939

I have to report that I found N^o 2 Shroud on the Starboard Fore Derrick Post; N^o 2 Shroud on the Port Main Derrick Post; Wasted and Fitted. Recommend these to be renewed. Main Mast: Wasted and Fitted in the body of the Mast. Recommend the Mast to be lifted out, scaled and cleaned for a further examination. Topmast: Feet to be examined when lifted out. Lower Shackles of all Rigging Crews to be Greed, Greed, and repaired where necessary. Derrick Posts, Spars, other Rigging and Ironwork in good condition.

A. D. Pearson

Fee £ : :

To the Surveyors,
Lloyd's Register of Shipping,
Sunderland

2m.11.29.



© 2021

Lloyd's Register
Foundation

W440-0047

COPY

UNIVERSITY OF TORONTO

Port of ...

January 11 1897

REPORT ON MASTS, SPARS AND RIGGING

Having in accordance with your instructions

examined the Masts, Spars, Iron Work of same, and Rigging of the

RETAIN

has been

If so, is the Report sent note or when will it be sent?

caus
on a
and
reple
the

In dam
offo

REPAI
Vea
Ena
cha
pip
ma
fre

W
K

AMMUS

PRESE

Decks
Caulkin
Coaming
Beams
Outside
Breasth
Transom
Frames
Reverse
Longitu
Transve
Floors
Keelson
Strings
Inner

Gen

Survey
Specia
Travel



© 2021

Lloyd's Register Foundation

10m.1.3

led not to write on or below the space for Committee's Minute.