

11.38.

17 JUN 39  
4 E

Inspected by Chief Engineer Surveyor .....

Received from Chief Engineer Surveyor .....

VESSEL'S NAME "TORO" Rpt. Skm. No. 4884

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/92.)

Particulars of Survey REPAIRS TO ENGINES ~~AND BOILERS~~ DUE TO DAMAGE THROUGH BROKEN JUNK

RING BOLT IN THE M.P. PISTON.

Piston rod faired and junk ring refitted.

It is submitted the vessel is eligible to remain as classed without fresh record of survey.



© 2020

Lloyd's Register  
Foundation  
W4410083

16.6.39

RETAIN

4

1984

1984



© 2020

Lloyd's Register  
Foundation

Did the S  
Did the S  
Did the S  
Has screw  
Has shaft  
Has the s  
State date  
Eng  
If so, did  
Has the i  
If the s  
broken  
Edyn  
place  
rene  
eve  
four  
Gene  
(Sta