

6 JUN 1939

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "ELENA R." Rpt. Ant. No. 2274

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

The class is subject to the solepiece of the sternframe (E.W.6,37) and to rudder repaired by E.W.8,25, 6,26, 2,27 and 6,37, being specially examined at the next drydocking.

The Antwerp Surveyors now report the vessel examined in dry dock, the bottom cleaned and coated, repairs effected to the steering engine and some riveting dealt with.

The E.W.repair to sternframe, as above, examined and found efficient and, in the Surveyors' opinion, the condition of class regarding same may now be deleted.

The E.W.repairs to rudder examined and slight fractures have been repaired by the same process and the Surveyors recommend special examination at the next drydocking.

Some corroded rivets were found in the keel plates and in the side plating but, in the Surveyors' opinion this riveting is efficient meantime and they recommend the former be dealt with at the next drydocking and the latter before the end of October, 1939.

It is submitted the vessel appears worthy to remain as classed with record of survey 5,39, subject as recommended and as above except as regards sternframe (rudder again E.W.5,39).

100A1) Subject etc.
5,39 Ant.) Without etc.
Fitted for oil fuel etc.

W442-0178



© 2020
5.6.39
Lloyd's Register
Foundation

Last
(Periodic
comple
extent
should
summa
should
respec
In dama
offer
REPAIR
SUMMAR
Ret
Ret
Fai
PRESENT
Deck
Caulking
Joamings
Beams & L
Outside Pl
" "
breasthook
transoms.
frames
leverses P
longitudin
transverse
floors
eelsons
tringers.
aner Bott
Gene
thi
sur
Elb
Aut
Corro
pla
Survey Fe
Special Da
(p

RECEIVED
NAME
DATE
NO.
BY

The results of the final ship survey are based on the case for the consideration of the Shipping Committee.
The following is a summary of the results of the survey and the recommendations of the Shipping Committee.
The results of the survey are as follows: 1. The ship is in good condition. 2. The hull is sound. 3. The machinery is in good condition. 4. The cargo gear is in good condition. 5. The deck is in good condition. 6. The interior is in good condition. 7. The exterior is in good condition. 8. The ship is in good condition. 9. The ship is in good condition. 10. The ship is in good condition.

The ship is in good condition. The hull is sound. The machinery is in good condition. The cargo gear is in good condition. The deck is in good condition. The interior is in good condition. The exterior is in good condition. The ship is in good condition. The ship is in good condition. The ship is in good condition.

The ship is in good condition. The hull is sound. The machinery is in good condition. The cargo gear is in good condition. The deck is in good condition. The interior is in good condition. The exterior is in good condition. The ship is in good condition. The ship is in good condition. The ship is in good condition.

The ship is in good condition. The hull is sound. The machinery is in good condition. The cargo gear is in good condition. The deck is in good condition. The interior is in good condition. The exterior is in good condition. The ship is in good condition. The ship is in good condition. The ship is in good condition.

The ship is in good condition. The hull is sound. The machinery is in good condition. The cargo gear is in good condition. The deck is in good condition. The interior is in good condition. The exterior is in good condition. The ship is in good condition. The ship is in good condition. The ship is in good condition.

The ship is in good condition. The hull is sound. The machinery is in good condition. The cargo gear is in good condition. The deck is in good condition. The interior is in good condition. The exterior is in good condition. The ship is in good condition. The ship is in good condition. The ship is in good condition.

The ship is in good condition. The hull is sound. The machinery is in good condition. The cargo gear is in good condition. The deck is in good condition. The interior is in good condition. The exterior is in good condition. The ship is in good condition. The ship is in good condition. The ship is in good condition.