

W446-0183

Part of R of S

Siedrecht

Rot. 17986

It is submitted that before this case receives consideration the Surveyors be requested to state whether the Safety valves of the original Donkey Boilers were adjusted to the approved working pressure or not what arrangements were made for this to be done, the reason for the renewal of the cylinder liners & covers & the purposes for which the new Donkey Boiler is intended to be used.

The Surveyors should also forward a sketch showing the position of the 3 Donkey Boilers relative to each other & state whether steam can pass from the new boiler to the others of lower pressure.

J.S.A.

Clg. Ltr. Rot. - 7/17/28

4/12/28



© 2020

Lloyd's Register Foundation

Survey
 " (No)
 Clg. Wh
 Clg. Ltr
 19
 Register Book
 Voyage
 Classification
 Register Bo
 by
 nd of
 2, 20
 9 etc.
 19
 under steam
 under steam
 Boiler?
 Boiler?
 Boiler?
 fitted at the a
 ng efficiently

IT IS REQUESTED NOT TO WRITE ACROSS THIS MARGIN

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Mounting plate on bearing metal of stern bush and top of after bearing of screw shaft?