

Surveyor there has apparently refused to allow the vessel to sail owing to the fact that her two after winches are out of order.

s.s. "STANCROFT"

It is submitted the Acting Surveyor at Barcelona be informed by telegram that winches and cargo gear do not come under the jurisdiction of this Society, and he is therefore not in order in recommending the vessel to be detained on account of these items.

14th November, 1938.

 © 2020  
Lloyd's Register  
Foundation  
W446-0312

STANCROFT did  
boiler trouble.—British United Press.

Barcelona, Oct. 13. — British steamer  
STANCROFT sprang a leak during a bomb-  
ardment of Barcelona this morning and  
according to latest reports is now sinking.

LOYD'S

er, or Y.M.  
State if o  
Then put o

s, Yards,  
tion, how  
State if u

ment lett

rs, No. of

Locker ...

(State i

length...

(on b

Rule leng

r & War

g and R

in the Regis  
tain as class

ema