

DEC 20 1938

No 4502

(Received at London Office)

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 28th Nov 1938 When handed in at Local Office 28th Nov 38 Port of Barcelona

No. in Reg. Book. Survey held at Barcelona Date, First Survey 31st Oct 1938 Last Survey 16th Nov 1938 (No. of Visits)

8398 on the Wood, Iron or Steel Sc "Stancroft" By whom J. Pristman & Co When 1908-11

TONNAGE—

GROSS 1402

UNDER DK. 1118

NET 282 865

Built at Sunderland

Owners Stanhope & Co

Managers J.A. Billmer & Co Ltd.

Owners' Address

(if not already recorded in Appendix to Register Book).

Port belonging to London

Surveyed Afloat or in Dry Dock? Yes Name of Dock Barcelona Destined Voyage

WB=Cell D Bor DBa feet; u&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4744 Port Mtl

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage stated to have been sustained during one raid at Barcelona on the 13th October 1938 by bomb dropped directly on the after deck in way of N.H. hatch. Damage found and repairs recommended as per enclosed Damage Report

REPAIR

SUMMARY OF DAMAGE REPAIRS:—

Renewed
Removed and Faird or Repaired
Faird or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors and Bracket Floors

Beams.

Inner Bottom Plates.

Dk. Plates.

Other Items:—

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Coamings

Beams & Fastenings

Outside Plating

" " in way of sidelights

Breasthooks

Transoms

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Dblg. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking ditto

Treenails ditto

Breasthooks & Stems ditto

Transoms Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto Ditto at other places ditto

Stringers, Clamps & Sheifs ditto

Salting (State if examined.)

Copper, or Y.M. of Wood Vessels

(State if on Belt).

When put on, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Chain Locker

Cables (State if now ranged)

" length mean diam.

(on board)

" Rule length size

Hawser & Warps

Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of 2, No. 1-24 and ptND24, &c."

This vessel is in efficient condition to remain as classed without fresh record of survey.

Survey Fee (per Section 29) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

Committee's Minute

Character Assigned

FRI, 23 DEC 1938

As noted

Subject

W446-0314

© 2020

Lloyd's Register Foundation