

Image 2/5  
Space  
Crown of  
Room ..

Depth "d," at middle of length (See Secs. 2 & 13) .... 12-16  
Proportions—Depths to Length—Upper Deck Beam at 1 9.26

Managers  
(Where necessary to be entered in Reg. Book.)

13 AUG 1920

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel S.S. "CRESWELL" Rpt. mif No. 2912.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

vey

The Surveyor should be requested to state thickness of deck plating in way of Engine and Boiler Space, depth & thickness of floors, if approved brackets to shell have been fitted at bulkheads, lengths of quarter deck & forecastle, & whether the record of "cem" should be made in this case. He should also state if the ventilators have been examined as required by Circular 1359.

The Superintendent at Lloyd's Proving House, Tipton, should be requested to forward particulars of Anchor Certificates Nos 47670, 47820 and 48347, and the Superintendent at Cradley Heath requested to forward particulars of Chain Cable Certificate No 23387.

m ltr 1987  
Chewington

2019  
12-8-20  
Lloyd's Register  
Foundation  
W447-0015

Brackets at intermdt. frmg., wdth & thknss

Tie Plates outside Hatchways .....

Deck \* Iron or Steel for



