

10 mm ✓ Are the shell plates welded or flanged and pl. flange? Description of riveting: circ. seams
inter. J.R. 53.8
52.9
45.2

4 E

17 DEC 1934

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

'S NAME

Rosario.

Rpt.

4453
4453a
4452
4452a.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Completion of Survey of Press Boilers.

It is submitted that
this vessel is eligible for
THE RECORD.

P.R. 8.33 subject to the Safety valves
of the 12 Hartman Boilers being adjusted
to 43 lb per sq. inch
Demand P. Boiler record to 26 P.B. both
12 " 43 lb.

Lloyd's Register
Foundation

Lower back plate: Material

Tensile strength

Thickness