

FRAMES, DOUBLE BOTTOM AND BEAMS.

W453-0134

F.E.

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME *Steel Sec. "CITY OF MANDALAY"* Rpt. *Inv.* No. *78729*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Longl.

Transverse No. *15208*

Depth "d" *19.33*

Framing: Table No. *2+3*

Description *Bull angle frames as approved*

Longitudinal No. *40681*

Proportions Length = *12.9* & *10.34*
Depth =

Deck Sheerstrake *as approved*

Revised Rules

This vessel appears to have been built in accordance with the *Revised* Rules and the approved plans, and it is submitted she is eligible to be classed **✚ 100 A.I.**

✚ 100 A.I. (steel)

2 Dks (stl) Cruiser stem.

Cell D.B. 374'. 1328t, D.T. a. 30' 928t.

F.K. 8.B.H. (1 to 2nd Dk), pt Cem. Lloyds A & C.P.

P43' B&F. 303'

It is concluded that the freeboard marks have been cut in on the ships side but the surveyors should be requested to state if this is so.

See letter
[Signature]



© 2020

Lloyd's Register Foundation