

It is concluded the cables are ~~2 3/16~~ to 2 1/16 and not as reported  
at the Surveyor should be requested to state if this is so.

hs 28.3.30

*[Signature]*



© 2020

Lloyd's Register  
Foundation

W455-0123