

JAN 29 1940

No. 50471

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 26 JAN 1940 Port of HULL
No. in Survey held at Hull Date, First Survey & Last Survey Jan 22nd 1940
eg. Book.24379 on the ~~Wood~~ ~~Iron~~ or Steel FARNDALE
TONNAGE:- Built at Sunderland By whom Sir J. Friedman & Co. When 1928 - 11
GROSS 4236 Owners Morrison S.S. Co. Ltd. Owners' Address
UNDER DE. 3946 Managers J. Morrison & Son Port belonging to Newcastle
NET 2581 Destined VoyageSurveyed Afloat or in Dry Dock? Drydock Name of Dock Alexandra
Cell D B or D Ba feet; uE&B feet; f feet
total capacity tons; FPT tons; APT tons; MT feet tons
Only alterations in the existing records of tanks should be inserted.N.B.—All alterations in the existing records should be underlined.
Last Report, No. 3062 Port P.N.2

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking
Vessel places in drydock. Bottom and rudder cleaned,
examined and coated. Examine holds & make generally,
S.R. List. Nothing done to items on this list.

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Decks <u>Part ex. good</u>	<u>Part ex. good</u>	<u>Good</u>	(State if on Felt.)
Caulking of Decks			When fitted, Month Year
Coamings			Boats
Beams & Fastenings			Masts, Yards, &c.
Outside Plating			Condition, how ascertained (State if wedges removed)
" " in way of sidelights			Equipment letter
Frames			Anchors, No. of
Reverse Frames			Cables (State if now ranged)
Longitudinals			" length (on board) mean diamr.
Transverses			" Rule length size
Floors			Chain Locker
Keelsons			Hawsers & Warps
Stringers			Standing and Running Rigging
Inner Bottom Plating			Sails
Have the Tanks been examined internally?			
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:-	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
State clearly whether any, and if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."		
<u>Eligible to remain as classed with fresh record of survey 1, 40. subject to permanent repairs to No. 4 shell plate in 3rd strake below sheer (s.s.) at Owners' convenience and to ash shoot first convenient opportunity. Indented plating (p.s.f.) in way of no. 5 hatch and framing in way and bow plating.</u>		

Survey Fee (per Section 29) £
Special Damage or Repair Fee (if any) (per Sec. 29) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £Fees applied for, 19
Received by me, 19W.S. Shields
Surveyor to Lloyd's Register of Shipping.Committee's Minute
Character Assigned

100771 subject with fl



© 2020

Lloyd's Register Foundation