

besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

88

2nd 11.38.

2 E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME "SEA RAMBLER".

Rpt. Nwc. No. 97973.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Signature of Surveyor..... COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS FOR S.S.~~ No.

This Survey, due 1,39 ~~now~~ partly held 12,38 now completed, and the following repairs carried out (due to grounding damage):-

Propeller renewed.

It is submitted the vessel is eligible to remain as classed, with notation of LMC 12,38, S 10,39 as recommended.

REMAIN



© 2020
YRM
Lloyd's Register
Foundation
1.11.39.
W 463 - 0208

valves, cocks, gunning,

Safety valves, cocks, gunning, etc.