

COPY.
RETAIN

SHANGHAI, Report No. 4092.

dated 23rd Sept., 1936.

M. V. "HORA MARRSK"

Damage due to Fire, Flooding & Beaching, Zamboanga, July, 1936.
Specification of repairs required to put the vessel in the same
condition as before the damage occurred.

N o t e ! In order that descriptions may agree with those of
Contractors and other Surveyors the terms Main Deck
& Upper Deck are taken to mean Second Deck & Shelter
Deck respectively.


Where parts are completely destroyed, e.g. furnishings,
fittings, instruments etc., translations of extracts
from the builder's specifications are quoted.

The sequence of items and numbering of pages is kept
the same as specifications in possession of the Owners'
& Underwriters' Representatives and Contractors.

The specification includes, as far as possible, removals
necessary to effect repairs and renewals.

*As there are deviations from
original specifications Owners are
arranging with underwriters, it is understood.*

RETAIN



© 2020

W464-0083 Lloyd's Register
Foundation